

Navy FMS QDR Process

- Receive QDR
 - Contract/Commerical Repairable
 - Submit QDR via PDREP to responsible DCMA that administered the contract. NAVSUP WSS is the originator, screening point and action point. DCMA acts as the support point
- Organic Repairable
 - Submit QDR via PDREP to Organic Depot. NAVSUP WSS acts as the originator and screening point. Organic Depot is the action point.
- Navy Stock (NRP Aviation)
 - Submit QDR as a SDR in PDREP

Navy FMS QDR Process

- Navy Stock (N35 Surface)
 - Submit QDR via PDREP to responsible DCMA that administered the contract. NAVSUP WSS is the originator, screening point and action point. DCMA acts as the support point.

DLA Stock

Submit QDR via WebSDR to SMS